

### LEGISLATIVE MEMORANDUM

TO: Honorable Mayor and Members of the City Council

FROM: Lisa Morrell, City Manager

DATE: June 20, 2019

### RE: FY 2019 Third Capital Improvements Program Amendment

The following is a summary of the revisions to the Capital Improvements Program/CIP in FY 2019.

### **Budget Amendment Modifications:**

- Growth Management Department Additional funding for transition to a new credit card processing company (Central Square) due to compatibility issues with the City's current vendor; capital portion of total funding request related to software purchase compatible with Track-It system; on Budget Amendment #3 - \$22,870.
- Finance Department Transfer \$83,479 from the General Fund (001) to the FY 2019 Road Program (project 19RD01) from City-owned property sales; on Budget Amendment #3 -\$83,479.
- 3. Police Department Purchase of one (1) 2019 Ford Transit Crime Scene Van; approved by Council 03/21/2019; on Budget Amendment #3 **\$29,139**.
- Public Works Department Funding to use Stormwater Utility Funds for design & construction of several Stormwater Utility Projects; approved by Council 03/07/2019; on Budget Amendment #3 \$2,100,000.
- 5. Public Works Department Additional funding for the Harper Boulevard @ C-18 Culvert Replacement Project (18SU14) due to unexpected costs discovered during the design process; approved by Council 03/07/2019; on Budget Amendment #3 **\$100,000**.
- Public Works Department Additional funding for the Cured in Place Pipe Project (19SU07) due to an increase in scope expenses; approved by Council 03/07/2019; on Budget Amendment #3 – \$120,000.
- Public Works Department Funding for the acquisition of additional Right of Way (ROW) four (4) vacant lots on Malabar Road for future expansion and reimbursement of appraisal costs; approved by Council 02/21/2019; on Budget Amendment #3 – \$57,000.

Down to Earth And Up To Great Things

Mayor and Council: FY 2019 Third Capital Improvements Program Amendment June 20, 2019 Page 2

### Transfer of Funds Between Capital Projects/Accounts:

- Utilities Department Budget Transfer #40 Transfer funds (\$562) from the Lift Stations RTU Replacement project (18WS10) to the Secondary Ponds Valve Improvements project (15WS05) \$562 to cover legal ad expenditures charged to the project - \$0.
- Utilities Department Budget Transfer #46 Transfer funds (\$48,900) from the Cable Lane Sewer Replacement project (14WS07) to the Cherry Hills Manhole Replacement project (19WS04) \$48,900; lowest project bid came in over budget - \$0.
- Utilities Department Budget Transfer #47 Transfer funds (\$73,428) from the Carbon Dioxide System project (19WS07) to the Filter Rehabilitation project (15WS02) \$73,428 to remove and replace valve position indicators (limit switches) and for additional concrete work - \$0.
- Public Works Department Budget Transfer #48 Close the completed RJ Conlan project (16PW14) (\$15,394) and transfer remaining funds to the FY 2019 Road Program (19RD01) \$15,394 - \$0.
- Public Works Department Budget Transfer #49 Close the completed Krassner Drive Repaving project (17PW09) (\$29,310) and transfer remaining funds to the FY 2019 Road Program (19RD01) \$29,310 - \$0.
- Public Works Department Budget Transfer #50 Close the completed Port Malabar & Palm Bay Road Left Turn project (18RD06) (\$7,445) and transfer remaining funds to the FY 2019 Road Program (19RD01) \$7,445 - \$0.
- Public Works Department Budget Transfer #51
   Transfer funds (\$150,000) from the Harper Blvd. @ C-18 Culvert project (18SU14) to the following projects to provide additional funding for construction costs: Culvert Replacement @ Garvey C17 (19SU02) \$50,000; Culvert Replacement @ Garvey C18 (19SU03) \$100,000-\$0.
- Public Works Department Budget Transfer #52
   Reprioritize and transfer funds (\$402,750) from the Unit 44 Replacement Pipe Crossing
   project (19SU05) and (\$402,750) from the Phase 2 Unit 44 Pipe Replacement project
   (19SU06) to the Unit 32 Pipe Replacement project (19SU09) \$805,500 - \$0.
- Public Works Department Budget Transfer #56
   Transfer funds \$1,105,500 from the following projects to the Unit 31 Pipeline Replacement
   project (19SU08): Pembroke Avenue @ C-75 Culver (18SU04) \$20,000; Emerson Drive @
   C-75 Culver (18SU06) \$70,000; Pebble Avenue @ C-75 Culver (18SU09) \$20,000; Harper
   Boulevard @ C-18 Culver (18SU14) \$140,000; San Filippo @ C-9-R Cross (18SU15)
   \$90,000; Unit 42 Pipe Replacement (18SU16) \$160,000; PH 2 Pipe Replacement Unit 42
   (19SU04) \$25,500; Unit 44 Replacement Pipe Crossing (19SU05) \$290,000; and Phase 2
   Unit 44 Pipe Replacement (19SU06) \$290,000 - \$0.

Down to Earth And Up To Great Things

Mayor and Council: FY 2019 Third Capital Improvements Program Amendment June 20, 2019 Page 3

10. Public Works Department – Budget Transfer #57

Transfer unused funds (\$39,649) from the Stormwater Retrofit South of Palm Bay Road project (17PW06) to the FY 19 Stormwater Utility Program (project 19SU01) \$39,649 for future project funding uses - **\$0**.

- 11. Bayfront Community Redevelopment Agency (BCRA) Budget Transfer #58 Close dredging projects Mooring Field & Dredging (16CR03) and Palm Bay Entrance Channel Dredging (18CR01) and transfer remaining funds to Land/Land Acquisitions for future use; both projects are not identified in the BCRA Redevelopment Plan resulting in discontinuation to proceed - **\$0**.
- 12. Utilities Department Budget Transfer #59 Transfer funds (\$112,991) from the Carbon Dioxide System project (19WS07) to the Filter Rehabilitation project (15WS02) \$112,991 for air release chamber repairs due to the failure of the existing concrete- **\$0**.
- Utilities Department Budget Transfer #60 Transfer funds from Machinery & Equipment (\$63,000) and the Treatment Unit Aerator Tray project (18WS20) (\$40,000) to the Spent Lime Sludge Dewatering project (19WS12) \$103,000 for engineering services/permitting - \$0.
- 14. Utilities Department Budget Transfer #61

Transfer funds \$258,225 from the following projects to the Sewer Pipe/Manhole Repair on U.S. 1 project (18WS30) based on received bid: North Regional RO Plant Rehab (16WS04) (\$250,000); Chlorine Analyzers Replacements (18WS17) (\$7,381); and SRWTP Bleach Pump # 4 Replacement (18WS29) (\$844) - **\$0**.

### Added/Removed Capital Projects, Addition/Reduction of Funding:

- Utilities Department Budget Transfer #44
   Transfer available non-capital funds from the Lift Station Repair/Maintenance expenses to the
   Lift Station 48 Rehabilitation project (19WS19) to due failure and proximity to Turkey Creek;
   possible sewage discharge could result in a violation and fines - \$44,640.
- 2. Utilities Department Budget Transfer #53

Funding for the installation of the Reuse TSS Meter at the North Regional Water Reclamation Facility was budgeted as capital outlay; the equipment will be installed on the system and general ledger account corrections are required. Transfer funds (\$29,100) from Capital Equipment and other non-capital expenses to the Reuse TSS Meter project (19WS20) \$30,600 – **Net Impact \$1,500**.

3. Utilities Department

FY 2020 CIP approved FX65 Trainer Mounted Vacuum Excavator totaling \$107,000 will no longer be purchased; available funds used towards the purchase of a GPS Unit totaling \$8,465. Outstanding balance of \$98,535 will remain in the 6401/Machinery & Equipment capital general ledger account for future use - **\$0**.

Down to Earth And Up To Great Things

Mayor and Council: FY 2019 Third Capital Improvements Program Amendment June 20, 2019 Page 4

### **REQUESTING DEPARTMENTS:**

Finance Department, Growth Management Department; Police Department; Public Works Department; Utilities Department; and Bayfront Community Redevelopment Agency (BCRA).

#### **RECOMMENDATION:**

Motion to adopt, by Resolution, the Third Amendment to the FY 19 Capital Improvements Program.

Attachment: 1) Resolution, Including Exhibit A

AC/ab

Down to Earth And Up To Great Things

### **RESOLUTION 2019-20**

A RESOLUTION OF THE CITY OF PALM BAY, BREVARD COUNTY, FLORIDA, AMENDING RESOLUTION 2018-49, AS AMENDED BY RESOLUTIONS 2018-66 AND 2019-10, ADOPTING THE FIVE-YEAR CAPITAL IMPROVEMENTS PROGRAM FOR THE FISCAL YEARS 2018-2019 THROUGH 2022-2023 FOR THE CITY OF PALM BAY; RESCINDING RESOLUTIONS OR PARTS OF RESOLUTIONS IN CONFLICT HEREWITH; PROVIDING FOR AN EFFECTIVE DATE.

WHEREAS, the City of Palm Bay's Capital Improvements Program, formally

known as the Community Investment Program, was adopted by the City Council on

September 18, 2016.

WHEREAS, the City of Palm Bay desires to amend the Capital Improvements Program.

NOW, THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY

OF PALM BAY, BREVARD COUNTY, FLORIDA, as follows:

**SECTION 1.** Resolution 2018-49, as amended by Resolutions 2018-66 and 2019-10, is hereby amended by including additional projects to the Five-Year Community Investment Program for Fiscal Years 2018-2019 through 2022-2023, which are, by reference, incorporated herein as Exhibit "A".

**SECTION 2.** This resolution shall take effect immediately upon the enactment date. This resolution was duly enacted at Meeting No. 2019-\_\_, of the City Council of the City of Palm Bay, Brevard County, Florida, on \_\_\_\_\_, 2019.

William Capote, MAYOR

ATTEST:

Terese M. Jones, CITY CLERK

### EXHIBIT "A" (Utilities Department)

| Fund   | Department<br>Division  | Project<br>Number   | Capital Improvements Program Summary   | FY 2019<br>Adopted CIP<br>Budget   | FY 2018<br>to<br>FY 2019  | FY 2019<br>Amendments   | New Project<br>TOTAL  | TOTAL FY 2019  |
|--|---|---|--|--|---|---|---|--|
|  |   |   |  | Dudget   | Rollovers   |   |   |  |
| tilities O   | perating  |   |  |  |   |   |   |  |
| 421  | 8010-536-6101   | 19WS01  | Utility Land Needs   | 100,000  | 0   | 0   | 100,000   | 100,0  |
| 421  | 8010-536-6403   | N/A   | Vehicle Replacements   | 23,000   | 0   | 0   | 23,000  | 23,0   |
| 421  | 8013-536-6401   | N/A   | Additional Vehicle Requests  | 22,000   | 0   | 0   | 22,000  | 22,0   |
| 421  | 8014-536-6401   | N/A   | Portable Ultrasonic Flow Meter   | 16,233   | 0   | 0   | 16,233  | 16,2   |
| 421  | 8014-536-6403   | N/A   | Vehicle Replacements   | 101,000  | 0   | 0   | 101,000   | 101,0  |
| 421  | 8018-536-6401   | N/A   | Glassware Dishwasher & Laboratory Refrigerator   | 12,600   | 0   | (3,782)   | 8,818   | 8,8  |
| 421  | 8020-533-6322   | N/A   | Meter Services - New Installations   | 245,000  | 0   | 0   | 245,000   | 245,0  |
| 421  | 8020-533-6401   | N/A   | Mini Excavator and Towmaster Trailer   | 76,000   | 0   | 0   | 76,000  | 76,0   |
| 421<br>421   | 8020-533-6401<br>8020-533-6401  | N/A<br>N/A  | Additional Water Distribution Equipment<br>FX65 Trainer Mounted Vacuum Excavator   | 54,632   | 0   | 0   | 54,632  | 54,  |
| 421  | 8020-533-6401   | N/A<br>N/A  | GPS Unit   | 107,000  | 0   | (107,000)<br>8,465  | 8,465   | 8,   |
| 421  | 8020-533-6401   | N/A   | Machinery & Equipment  | 0  | 0   | 35,535  | 35,535  | 35,  |
| 421  | 8020-533-6403   | N/A   | Vehicle Replacements   | 122,000  | 0   | 0   | 122,000   | 122,   |
| 421  | 8020-533-6403   | 17WS02  | I-95/Parkway WM and FM   | 0  | 16,712  | 0   | 16,712  | 122,16,  |
| 421  | 8024-533-6309   | 17W302<br>18WS23  | NRWTP Rear Yard Swale & Fenc Imprs   | 0  | 48,357  | 7,619   | 55,976  | 55,  |
| 421  | 8024-533-6305   | 18WS20  | NRWTP Treatment Unit Aerator Tray  | 0  | 40,000  | (40,000)  | 0   |  |
| 421  | 8024-533-6221   | 19WS12  | NRWTP Sludge Dewatering  | 0  | 40,000  | 103,000   | 103,000   | 103,   |
| 421  | 8024-533-6221   | 19WS12<br>18WS23  | NRWTP Studge Dewatering<br>NRWTP Rear Yard Swale & Fenc Imprs  | 0  | 18,173  | 103,000   | 18,173  | 103,   |
| 421  | 8024-535-6325   | 18W323<br>17WS02  | I-95/Parkway WM and FM   | 0  | 16,712  | 0   | 16,712  | 18   |
| 421  | 8030-535-6325   | 17WS02<br>16WS07  | Palm Vista Lift Station  | 0  | 1,320,319   | 0   | 1,320,319   | 1,320  |
| 421  | 8030-535-6327   | N/A   | Additional Vehicle Requests  | 43,000   | 1,320,319   | 0   | 43,000  | 43   |
| 421  | 8030-535-6401   | N/A<br>N/A  | Combination Sewer Cleaner and Nozzles  | 43,000   | 0   | 0   | 43,000  | 43   |
| 421  |   | N/A<br>17WS13   | Combination Sewer Cleaner and Nozzles  |  | Ç   |   | -   |  |
| 421  | 8034-535-6221<br>8034-535-6221  | 17WS13<br>17WS16  | WRF Denitrification Project  | 0  | 2,290<br>1,315,548  | 0   | 2,290<br>1,315,548  | 2 1,315  |
|  |   |   | -  |  |   |   |   |  |
| 421  | 8034-535-6221   | 19WS20  | Reuse TSS Meter Installation   | 0  | 0   | 30,600  | 30,600  | 30   |
| 421  | 8034-535-6401   | N/A   | Reuse TSS Meters   | 29,100   | 0   | (29,100)  | 0   |  |
|  |   |   |  |  |   |   |   |  |
|  | onnections Fee Fund   | 1014/004  |  | -  | 540.000   | 240.000   | 750.000   | 750  |
| 423  |   | 18WS04  | SRWTP Expansion  | 0  | 510,000   | 249,806   | 759,806   | 759  |
| 423  |   | 17WS03  | Cogan Drive WM and FM  | 0  | 14,439  | 0   | 14,439  | 14,  |
| 423  |   | 19WS14  | Culver Drive Utility Relocations   | 109,109  | 0   | 0   | 109,109   | 109  |
| 423  | 8031-535-6221   | 16WS05  | South Regional Water Reclamation Fac   | 0  | 13,681  | 6,312   | 19,993  | 19   |
| 423  |   | 17WS03  | Cogan Drive WM and FM  | 0  | 101,855   | (6,312)   | 95,543  | 95,  |
| 423  | 8031-535-6327   | 17WS08  | I-95 I/C Regional Lift Station   | 0  | 115,000   | 0   | 115,000   | 115,   |
|  |   |   |  |  |   |   |   |  |
|  | enewal and Replacem   |   |  |  |   |   |   |  |
| 424  |   | 12WS02  | Repl of Large Diameter Steel Pipe  | 0  | 1,001,037   | 0   | 1,001,037   | 1,001  |
| 424  |   | 14WS01  | .5 mg Storage Tank Repair  | 0  | 48,560  | 0   | 48,560  | 48,  |
| 424  | 8022-533-6221   |   | Filter Rehabilitation  | 0  | 311,668   | 186,419   | 498,087   | 498,   |
|  |   | 15WS02  |  |  |   |   | -   | -  |
| 424  | 8022-533-6221   | 16WS01  | Treatment Unit Rehabilitation  | 1,440,000  | 9,520   | 279,602   | 1,729,122   | 1,729  |
| 424  | 8022-533-6221<br>8022-533-6221  | 16WS01<br>16WS04  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab   | 1,440,000<br>112,000   | 9,520<br>138,000  | 279,602<br>(250,000)  | 1,729,122<br>0  | 1,729  |
| 424<br>424   | 8022-533-6221<br>8022-533-6221<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump   | 1,440,000<br>112,000<br>0  | 9,520<br>138,000<br>306,319   | 279,602<br>(250,000)<br>0   | 1,729,122<br>0<br>306,319   | 1,729<br>306   |
| 424<br>424<br>424  | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221  | 16WS01<br>16WS04<br>17WS04<br>18WS02  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement   | 1,440,000<br>112,000<br>0<br>0   | 9,520<br>138,000<br>306,319<br>18,719   | 279,602<br>(250,000)<br>0<br>(11,107)   | 1,729,122<br>0<br>306,319<br>7,612  | 1,729<br>306<br>7  |
| 424<br>424<br>424<br>424   | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl  | 1,440,000<br>112,000<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798   | 1,729<br>306<br>7<br>466   |
| 424<br>424<br>424<br>424<br>424<br>424                             | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl   | 1,440,000<br>112,000<br>0<br>420,000<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873   | 279,602<br>(250,000)<br>0<br>(11,107)   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492   | 1,729<br>306<br>7<br>466<br>40   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424                      | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl  | 1,440,000<br>112,000<br>0<br>0<br>420,000  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936  | 1,729<br>306<br>7<br>466<br>40<br>40   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424               | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424                      | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab   | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424               | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6318<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>49,711<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6318  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0  | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>49,711  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6318<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>49,711<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000  | 1,729<br>306<br>7<br>466<br>40<br>467<br>15<br>63<br>49<br>85<br>359   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6318<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System   | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0  | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>49,711<br>0<br>(186,419)  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581   | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS08  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000   | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>359<br>53<br>75  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS08<br>19WS10  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Chlorine Analyzers Repl<br>SRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement   | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>546,000<br>53,000<br>75,000  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000   | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>53<br>63<br>49<br>85<br>359<br>53<br>75<br>50   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS08<br>19WS010<br>19WS11   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000   | 1,729<br>306<br>7<br>466<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>103  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6322  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS03<br>19WS07<br>19WS08<br>19WS08<br>19WS10<br>19WS11  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Chlorine Analyzers Repl<br>SRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering  | 1,440,000<br>112,000<br>0<br>0<br>420,000<br>0<br>438,000<br>0<br>438,000<br>0<br>0<br>0<br>0<br>0<br>0<br>53,000<br>53,000<br>50,000<br>103,000   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>50,000   | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>359<br>53<br>53<br>75<br>50<br>103<br>175  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6322<br>8022-533-6324  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements   | 1,440,000         112,000         0         0         420,000         420,000         438,000         0         438,000         0         438,000         0         438,000         0         0         438,000         53,000         50,000         103,000         175,000  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>50,000<br>103,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>53<br>63<br>49<br>85<br>359<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>75<br>50<br>103<br>175<br>307  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6324<br>8022-533-6324  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS02   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Chlorine Analyzers Repl<br>SRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects   | 1,440,000         112,000         0         0         420,000         420,000         0         438,000         0         438,000         0         438,000         0         0         0         53,000         53,000         50,000         103,000         175,000         307,800   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>103,000<br>103,000<br>175,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>53<br>53<br>53<br>75<br>50<br>103<br>175<br>307<br>148   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6324<br>8022-533-6324<br>8022-533-6324   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS08<br>19WS00<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS02<br>19WS06   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Chlorine Analyzers Repl<br>SRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement Program  | 1,440,000         112,000         0         0         420,000         0         420,000         0         438,000         0         438,000         0         438,000         0         438,000         0         53,000         53,000         50,000         103,000         175,000         307,800         148,000   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>53<br>63<br>49<br>85<br>359<br>53<br>53<br>55<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>148<br>3135   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6324<br>8022-533-6324<br>8022-533-6324   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS08<br>19WS00<br>19WS11<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS09   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club   | 1,440,000         112,000         0         0         420,000         0         420,000         0         438,000         0         438,000         0         0         438,000         53,000         50,000         103,000         175,000         307,800         148,000         135,500  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6318         8022-533-6318         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS09<br>19WS03   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements  | 1,440,000         112,000         0         0         420,000         420,000         0         438,000         0         438,000         0         438,000         0         438,000         0         53,000         53,000         50,000         103,000         175,000         307,800         148,000         188,000   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000  | 1,729<br>306<br>7<br>466   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6318<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6221<br>8022-533-6324<br>8022-533-6324<br>8022-533-6324<br>8022-533-6324  | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS00<br>19WS10<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS09<br>19WS03<br>19WS13   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations  | 1,440,000           112,000           0           0           420,000           0           420,000           0           438,000           0           438,000           0           0           438,000           0           0           438,000           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           53,000           50,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000<br>135,500<br>188,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>53<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>50<br>103<br>175<br>307<br>103<br>175<br>307<br>148<br>135<br>188<br>163<br>215  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6318           8022-533-6318           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS09<br>19WS03<br>19WS04<br>19WS14<br>15WS05   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements  | 1,440,000           112,000           0           0           420,000           0           420,000           0           438,000           0           438,000           0           0           438,000           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>50,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000<br>135,500<br>188,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>55<br>63<br>49<br>85<br>359<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53<br>53   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6221         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8022-533-6324         8032-535-6221         8032-535-6221         8032-535-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS06<br>19WS09<br>19WS03<br>19WS04<br>15WS05   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement Program<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements   | 1,440,000           112,000           0           0           420,000           0           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           0           0           0           53,000           53,000           50,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>359,581<br>53,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000<br>135,500<br>188,000<br>163,664<br>215,997<br>26,472   | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>53<br>53<br>53<br>53<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>48<br>135<br>188<br>135<br>188<br>163<br>215<br>26  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6318           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS09<br>19WS03<br>19WS05<br>15WS07<br>18WS01<br>18WS01  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Chlorine Analyzers Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation  | 1,440,000           112,000           0           0           420,000           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           0           0           0           0           0           0           0           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           0           0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>10,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,0000<br>100 | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>53<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>148<br>135<br>188<br>163<br>215<br>26<br>566<br>355   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS12<br>19WS06<br>19WS02<br>19WS06<br>19WS05<br>19WS05<br>15WS07<br>18WS01<br>18WS01<br>18WS09<br>18WS14   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Chlorine Analyzers Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement   | 1,440,000         112,000         0         0         420,000         0         420,000         0         438,000         0         438,000         0         438,000         0         438,000         0         0         0         0         0         0         0         0         53,000         53,000         53,000         50,000         103,000         175,000         307,800         148,000         135,500         188,000         163,664         0         0         0         0         0         0         0         0         0         0         0         0         0         0         0         0         0         0         0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>0<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>50,000<br>103,000<br>103,000<br>175,000<br>307,800<br>148,000<br>135,500<br>148,000<br>135,500<br>148,000<br>163,664<br>215,997<br>26,472<br>566,000<br>355,619<br>370,732   | 1,729<br>306<br>7<br>466<br>400<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>53<br>53<br>53<br>103<br>175<br>307<br>103<br>175<br>307<br>148<br>135<br>188<br>163<br>215<br>26<br>566<br>355<br>370  |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS10<br>19WS10<br>19WS12<br>N/A<br>19WS12<br>N/A<br>19WS02<br>19WS06<br>19WS09<br>19WS03<br>19WS05<br>15WS07<br>18WS01<br>18WS01<br>18WS01  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation  | 1,440,000           112,000           0           0           420,000           0           438,000           0           438,000           0           438,000           0           0           438,000           0           0           0           0           0           0           0           0           0           53,000           546,000           53,000           50,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(0<br>(0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,1220306,3197,612466,79840,492467,93615,83463,87849,71185,000359,58153,00075,00050,000103,000175,000307,800148,000135,500188,000163,664215,99726,472566,000355,619370,732472,507   | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>5<br>5<br>3<br>5<br>3<br>5<br>3<br>5<br>3<br>5<br>3<br>5<br>3<br>5<br>3<br>5<br>3<br>5<br>3   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS07<br>19WS08<br>19WS10<br>19WS12<br>N/A<br>19WS02<br>19WS02<br>19WS06<br>19WS09<br>19WS03<br>19WS05<br>15WS07<br>18WS01<br>18WS01<br>18WS01<br>18WS01<br>18WS05   | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation<br>AquaDisk System Upgrade   | 1,440,000           112,000           0           0           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           0           0           53,000           53,000           53,000           50,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0  | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(0<br>(186,419)<br>0<br>(0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>0<br>(0)<br>(0) | 1,729,122<br>0<br>3306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,000<br>100,0000<br>100,00000000                      | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>148<br>135<br>188<br>163<br>215<br>26<br>566<br>355<br>370<br>472   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221 | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS00<br>19WS10<br>19WS10<br>19WS10<br>19WS10<br>19WS12<br>19WS05<br>19WS05<br>19WS05<br>15WS07<br>18WS01<br>18WS01<br>18WS05<br>18WS14<br>18WS15<br>19WS05<br>14WS07  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation<br>AquaDisk System Upgrade<br>Cable Lane Sewer Replacement   | 1,440,000           112,000           0           0           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           438,000           0           0           0           0           0           0           53,000           53,000           53,000           50,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           163,664           0           0           0           0           0           0           0           0           0           0      0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,1220306,3197,612466,79840,492467,93615,83463,87849,71185,000359,58153,00075,00050,000103,000175,000307,800148,000135,500188,000163,664215,99726,472566,000355,619370,732472,50729,050343,198  | 1,729<br>306<br>7<br>466<br>400<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>148<br>135<br>188<br>163<br>215<br>26<br>566<br>355<br>370<br>472<br>29<br>343   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6325           8032-535-6325 | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS10<br>19WS12<br>N/A<br>19WS12<br>N/A<br>19WS12<br>19WS05<br>19WS05<br>15WS07<br>18WS01<br>18WS01<br>18WS05<br>18WS01<br>18WS05<br>18WS05  | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement Program<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation<br>AquaDisk System Upgrade<br>Cable Lane Sewer Replacement<br>ARV Upgrade Program   | 1,440,000           112,000           0           0           420,000           420,000           438,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           53,000           53,000           53,000           53,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0 <td>9,520<br/>138,000<br/>306,319<br/>18,719<br/>46,798<br/>47,873<br/>29,936<br/>16,678<br/>63,878<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0</td> <td>279,602<br/>(250,000)<br/>(11,107)<br/>(11,107)<br/>0<br/>(7,381)<br/>0<br/>(844)<br/>0<br/>(844)<br/>0<br/>(844)<br/>0<br/>(186,419)<br/>(186,419)<br/>0<br/>(186,419)<br/>0<br/>(186,419)<br/>0<br/>(186,419)<br/>0<br/>(0<br/>(186,419)<br/>0<br/>(0<br/>(0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0<br/>0</td> <td>1,729,122<br/>0<br/>306,319<br/>7,612<br/>466,798<br/>40,492<br/>467,936<br/>15,834<br/>63,878<br/>49,711<br/>85,000<br/>359,581<br/>53,000<br/>75,000<br/>50,000<br/>103,000<br/>103,000<br/>175,000<br/>307,800<br/>103,000<br/>175,000<br/>307,800<br/>148,000<br/>135,500<br/>148,000<br/>135,500<br/>188,000<br/>163,664<br/>215,997<br/>26,472<br/>566,000<br/>355,619<br/>370,732<br/>472,507<br/>29,050<br/>343,198</td> <td>1,729<br/>306<br/>7<br/>466<br/>40<br/>40<br/>467<br/>15<br/>63<br/>49<br/>85<br/>359<br/>53<br/>75<br/>50<br/>103<br/>175<br/>50<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>175<br/>307<br/>103<br/>103<br/>103<br/>103<br/>103<br/>103<br/>103<br/>103</td> | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(0<br>(186,419)<br>0<br>(0<br>(0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,122<br>0<br>306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>50,000<br>103,000<br>103,000<br>175,000<br>307,800<br>103,000<br>175,000<br>307,800<br>148,000<br>135,500<br>148,000<br>135,500<br>188,000<br>163,664<br>215,997<br>26,472<br>566,000<br>355,619<br>370,732<br>472,507<br>29,050<br>343,198  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>175<br>307<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6325           8032-535-6325           8032-535-6325   | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS12<br>19WS06<br>19WS02<br>19WS03<br>19WS03<br>19WS05<br>15WS07<br>18WS05<br>18WS01<br>18WS09<br>18WS14<br>15WS05<br>15WS07<br>18WS01<br>18WS09<br>18WS14<br>18WS09                               | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>ScADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation<br>AquaDisk System Upgrade<br>Cable Lane Sewer Replacement<br>ARV Upgrade Program<br>Sewer Pipe/Manhole Repair (US #1/TC)  | 1,440,000           112,000           0           0           420,000           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           0           0           0           0           53,000           53,000           53,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(0<br>(0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>3306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>50,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>53<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>50<br>103<br>75<br>50<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6325           8032-535-6325           8032-535-6325           8032-535-6325           8032-535-6325           8032-535-6325 | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS10<br>19WS10<br>19WS10<br>19WS12<br>N/A<br>19WS12<br>19WS05<br>19WS05<br>19WS05<br>15WS07<br>18WS01<br>18WS01<br>18WS01<br>18WS05<br>15WS07<br>18WS01<br>18WS05<br>15WS07<br>18WS01<br>18WS03<br>18WS14<br>18WS05<br>14WS07<br>18WS05 | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP High Service Pumps Repl<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>SCADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation<br>AquaDisk System Upgrade<br>Cable Lane Sewer Replacement<br>ARV Upgrade Program<br>Sewer Pipe/Manhole Repair (US #1/TC)<br>Public Works Utility Relocation Projects | 1,440,000           112,000           0           0           420,000           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           0           0           0           0           53,000           53,000           50,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           163,664           0           0           0           0           0           0           0           0           0           0           0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>0<br>(186,419)<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 1,729,1220306,3197,612466,79840,492467,93615,83463,87849,71185,000359,58153,00075,00050,000103,000175,000307,800148,000135,500188,000163,664215,99726,472566,000355,619370,732472,50729,050343,19891,30280,00048,000  | 1,729<br>306<br>7<br>466<br>400<br>467<br>15<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>148<br>135<br>188<br>163<br>215<br>26<br>566<br>355<br>370<br>472<br>29<br>343<br>91<br>80   |
| 424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424<br>424 | 8022-533-6221           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8022-533-6324           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6221           8032-535-6325           8032-535-6325           8032-535-6325           8032-535-6325           8032-535-6325           8032-535-6325 | 16WS01<br>16WS04<br>17WS04<br>18WS02<br>18WS06<br>18WS17<br>18WS19<br>18WS29<br>17WS22<br>19WS17<br>19WS03<br>19WS07<br>19WS03<br>19WS07<br>19WS08<br>19WS10<br>19WS11<br>19WS12<br>N/A<br>19WS12<br>19WS06<br>19WS02<br>19WS03<br>19WS03<br>19WS05<br>15WS07<br>18WS05<br>18WS01<br>18WS09<br>18WS14<br>15WS05<br>15WS07<br>18WS01<br>18WS09<br>18WS14<br>18WS09                               | Treatment Unit Rehabilitation<br>NO Reg RO Plant Rehab<br>Tsf Filter/Backwash Pump<br>NRWTP Slaker Replacement<br>NRWTP Slaker Replacement<br>NRWTP Chlorine Analyzers Repl<br>NRWTP Generator & Air Compressor Repl<br>SRWTP Bleach Pump #4<br>Well 17 Rehab<br>Rehabilitation of Water Wells<br>South Regional WPT Feed Line Restoration<br>Carbon Dioxide System<br>Sodium Hypochlorite Pump Skid Replacement<br>Nash Street High Service Pump Replacement<br>NRWTP Lime Slaking Silo Replacement<br>Spent Lime Sludge Dewatering<br>Meter Services - Replacements<br>Public Works Utility Relocation Projects<br>Valve Replacement - Country Club<br>Fire Hydrant Replacements<br>Culver Drive Utility Relocations<br>Secondary Ponds Valve Improvements<br>ScADA Improvements<br>Reuse High Service Pumps Repl<br>WWTP Digester 6 Rehabilitation<br>WWTP Bar Screen Replacement<br>RAS/WAS Pump Rehabilitation<br>AquaDisk System Upgrade<br>Cable Lane Sewer Replacement<br>ARV Upgrade Program<br>Sewer Pipe/Manhole Repair (US #1/TC)  | 1,440,000           112,000           0           0           420,000           420,000           0           438,000           0           438,000           0           438,000           0           438,000           0           0           0           0           0           0           0           0           0           53,000           53,000           53,000           103,000           175,000           307,800           148,000           135,500           188,000           163,664           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0           0   | 9,520<br>138,000<br>306,319<br>18,719<br>46,798<br>47,873<br>29,936<br>16,678<br>63,878<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                          | 279,602<br>(250,000)<br>(11,107)<br>(11,107)<br>0<br>(7,381)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(844)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(186,419)<br>0<br>(0<br>(0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 1,729,122<br>0<br>3306,319<br>7,612<br>466,798<br>40,492<br>467,936<br>15,834<br>63,878<br>49,711<br>85,000<br>359,581<br>53,000<br>75,000<br>50,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000<br>103,000  | 1,729<br>306<br>7<br>466<br>40<br>40<br>467<br>55<br>63<br>49<br>85<br>359<br>53<br>75<br>50<br>103<br>175<br>50<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>307<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>175<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103<br>103 |

## EXHIBIT "A" (Utilities Department)

| Fund        | Department<br>Division | Project<br>Number | Capital Improvements Program Summary            | FY 2019<br>Adopted CIP<br>Budget | FY 2018<br>to<br>FY 2019<br>Rollovers | FY 2019<br>Amendments | New Project<br>TOTAL | TOTAL FY 2019 |
|-------------|------------------------|-------------------|---|----------------------------------|---------------------------------------|-----------------------|----------------------|---------------|
| 424         | 8032-535-6327          | 18WS10            | Lift Stations RTU Replacment Prog               | 169,612                          | 169,612                               | (24,258)              | 314,966              | 314,966       |
| 424         | 8032-535-6327          | 18WS11            | Lift Station Electrical Panel Repl Prog         | 143,325                          | 136,500                               | 0                     | 279,825              | 279,825       |
| 424         | 8032-535-6327          | 18WS21            | Lift Station Valve Pit Elimination Prog         | 0                                | 239,299                               | 0                     | 239,299              | 239,299       |
| 424         | 8032-535-6327          | 19WS19            | Rehab Lift Station 48                           | 0                                | 0                                     | 44,640                | 44,640               | 44,640        |
| Main Line I | Extension Fee Fund     |                   |   |                                  |                                       |                       |                      |               |
| 425         | 8021-533-6324          | 18WS07            | Palm Bay Hospital Water Main Loop               | 0                                | 168,000                               | 0                     | 168,000              | 168,000       |
| 425         | 8021-533-6324          | 19WS15            | Garvey Road SW Water Main Line Extension        | 130,152                          | 0                                     | 0                     | 130,152              | 130,152       |
| 425         | 8021-533-6324          | 19WS16            | Water Main Line Extension - Franklin & Walmsley | 29,000                           | 0                                     | 0                     | 29,000               | 29,000        |
|             |                        |                   | TOTAL UTILITY DEPARTMENT ONLY                   | 7,953,154                        | 8,145,564                             | 370,871               | 16,469,589           | 16,469,589    |

# EXHIBIT "A" (Non-Utility Departments)

| Fund               | Department<br>Division                  | Project<br>Number | Capital Improvements Program Summary                                  | FY 2019<br>Adopted CIP<br>Budget | FY 2018<br>to<br>FY 2019 Rollovers | FY 2019<br>Amendments | New Project TOTAL    | TOTAL FY 2019        |
|--------------------|---|-------------------|---|----------------------------------|------------------------------------|-----------------------|----------------------|----------------------|
| Communica          | itions & Informatio                     | n Technology      | v   |                                  |                                    |                       |                      |                      |
| 001                | 2310-519-6413                           | 18IT01            | VOIP Network & Telephone Upgrade                                      | 0                                | 471,576                            | 0                     | 471,576              | 471,576              |
| 001                | 2310-519-6413                           | 18IT02            | HD Video Upgrade-Council Chambers                                     | 0                                | 46,690                             | 0                     | 46,690               | 46,690               |
| 001                | 2310-519-6413                           | N/A               | Network Equipment   | 0                                | 435,632                            | 0                     | 435,632              | 435,632              |
| Facilities         | 4525-519-6201                           | 14PW07            | PW Crew Building  | 0                                | 42 519                             | 10 005                | E4 952               | E4 953               |
| 001<br>001         | 4525-519-6201                           | 14PW07<br>18FM03  | Honeywell Performance   | 0                                | 42,518<br>2,587,040                | 12,335<br>0           | 54,853<br>2,587,040  | 54,853<br>2,587,040  |
| Police             |   |                   |   |                                  |                                    |                       |                      |                      |
| 101                | 5040-521-6401                           | N/A               | Latitude Fentanyl Filtered Hood                                       | 0                                | 79                                 | 8,350                 | 8,429                | 8,429                |
| 101                | 5040-521-6403                           | N/A               | 2019 Ford Transit T150 Crime Scene Van/Light Vehicles                 | 0                                | 0                                  | 29,136                | 29,136               | 29,136               |
| Fire               | 6042 522 6204                           | 405504            |   |                                  |                                    | 200.000               | 200.000              |                      |
| 001                | 6012-522-6201<br>6012-522-6405          | 18FD01<br>18FD01  | Fire Station #5<br>Fire Station #5                                    | 0 300,000                        | 06,890                             | 300,000 (300,000)     | 300,000<br>6,890     |                      |
| 001                | 6012-522-6401                           | N/A               | Generator - Fire Station #2   | 30,000                           | 0                                  | 0                     | 30,000               | 30,000               |
| 153                | 6050-522-6201                           | 18FD01            | Fire Station #5   | 80,000                           | 0                                  | 0                     | 80,000               | 80,000               |
| Growth Ma          | nagement                                |                   |   |                                  |                                    |                       |                      |                      |
| 111                | 3353-554-6201                           | 14CD01            | Homes for Warriors  | 0                                | 307,874                            | 0                     | 307,874              | 307,874              |
| 111                | 3353-554-6201                           | 17CD03            | Homes/Warriors Hunt St<br>Portion of Fire Station 5 Rebuild           | 0                                | 7,354                              | 0                     | 7,354                | 7,354                |
| 112<br>112         | 3353-554-6201<br>3353-554-6308          | 18FD01<br>14CDBG  | Portion of Fire Station 5 Rebuild<br>Uncommitted & Available Funds    | 337,315                          | 452,447<br>572,425                 | 0                     | 789,762<br>572,425   | 789,762              |
| 112                | 3353-554-6201                           | 14CD80<br>14CD01  | Homes for Warriors  | 0                                | 95,621                             | 0                     | 95,621               | 95,621               |
| 451                | 3320-524-6403                           | N/A               | Replacement Vehicles (2) for Building Fleet                           | 45,000                           | 0                                  | 0                     | 45,000               | 45,000               |
| 451<br>451         | 3320-524-6407<br>3320-524-6407          | N/A<br>N/A        | Trak-It Software Purchase<br>Credit Card Processing (Central Square)  | 0                                | 508,960<br>0                       | 25,500<br>22,870      | 534,460<br>22,870    | 534,460<br>22,870    |
|                    |   |                   |   | 0                                | 0                                  | 22,070                | 22,070               | 22,670               |
| Parks & Rec<br>001 | 4026-572-6332                           | 19PR01            | West Oaks Playground Replacement                                      | 90,000                           | 0                                  | 0                     | 90,000               | 90,000               |
| 001                | 4026-572-6301                           | 19PR05            | Oakwood Basketball Resurfacing  | 0                                | 0                                  | 12,000                | 12,000               | 12,000               |
| 301<br>154         | 4090-572-6308<br>4050-572-6301          | 16PK08<br>18PR01  | Campground @ PB Reg Park<br>MUSCO Control Link/Ballfield Lights       | 0                                | 1,697,195<br>101,000               | 0                     | 1,697,195<br>101,000 | 1,697,195<br>101,000 |
| 154                | 4050-572-6308                           | 16PK08            | Campground @ PB Reg Park  | 0                                | 50,303                             | 0                     | 50,303               | 50,303               |
| 154                | 4050-572-6308                           | 18PR04            | Wake Foreset BB Court   | 0                                | 80,816                             | 0                     | 80,816               | 80,816               |
| 154                | 4050-572-6401                           | N/A               | Turf Equipment  | 0                                | 0                                  | 12,320                | 12,320               | 12,320               |
| 154<br>154         | 4050-572-6401<br>4050-572-6332          | N/A<br>17PR06     | Additional Movie Equipment<br>PB Senior Ctr Imprvs                    | 0                                | 0<br>4,321                         | 36,000<br>0           | 36,000<br>4,321      | 36,000<br>4,321      |
| Public Work        | (5                                      |                   |   |                                  |                                    |                       |                      |                      |
| 155                | 7050-541-6303                           | 19PW01            | Emerson Reconstruction  | 50,000                           | 0                                  | 0                     | 50,000               | 50,000               |
| 155                | 7050-541-6316                           | 18PW01            | SJHP Traffic Signal @ Malabar   | 0                                | 298,289                            | 0                     | 298,289              | 298,289              |
| 155<br>155         | 7050-541-6316<br>7050-541-6101          | 16PW13<br>N/A     | Culver Street<br>Land Acquisition - Four (4) Lots/ROW Malabar Rd.     | 0                                | 1,961,967                          | 147,413<br>57,000     | 2,109,380<br>57,000  | 2,109,380            |
| 301                | 7090-539-6301                           | 13PW02            | Bus Shelter Installation  | 0                                | 146,086                            | 0                     | 146,086              | 146,086              |
| 301                | 7090-541-6315                           | 18PW02            | Safe Route to Schools   | 0                                | 132,100                            | 0                     | 132,100              | 132,100              |
| 306                | 7090-541-6303                           |                   | South I-95 Interchange/Pkwy   | 0                                | 755,710                            | 0                     | 755,710              | 755,710              |
| 307                | 7090-541-6304<br>7090-541-6304          | 16PW13            | Culver St   | 0                                | 9,353                              | (15.204)              | 9,353                | 9,353                |
| 307<br>307         | 7090-541-6304                           | 16PW14<br>17PW09  | RJ Conlan<br>Krassner Dr Repaving                                     | 0                                | 1,024,180<br>61,172                | (15,394)<br>(29,310)  | 1,008,786<br>31,862  | 1,008,786<br>31,862  |
| 307                | 7090-541-6304                           | 17PW10            | Garvey Rd Repaving  | 0                                | 17,383                             | 0                     | 17,383               | 17,383               |
| 307                | 7090-541-6304                           |                   | Eldron Blvd Repaving  | 0                                | 6,166                              | 0                     | 6,166                | 6,166                |
| 307                | 7090-541-6304                           | 18RD01            | FY 18 Road Program  | 0                                | 1,096,269                          | (1,096,269)           | 0                    | C                    |
| 307<br>307         | 7090-541-6304<br>7090-541-6304          | 18RD06<br>18RD07  | Malabar @ PB Rd Left Turn Reconfiguration<br>Malabar Rd Widen Prelim. | 0                                | 65,000<br>12,450                   | (7,445)               | 57,555<br>12,450     | 57,555               |
| 307                | 7090-541-6304                           |                   | FY 19 Road Program  | 200,000                          | 0                                  | 2,020,207             | 2,220,207            | 2,220,207            |
| 307                | 7090-541-6304                           |                   | Rejuvenation of 7 City Roads  | 0                                | 0                                  | 50,000                | 50,000               | 50,000               |
| 307<br>307         | 7090-541-6315<br>7090-541-6331          | 18PW02<br>18RD05  | Safe Route to Schools Dynamic Speed Feedback Signs (DSFS)             | 0                                | 326                                | 1,950<br>0            | 2,276                | 2,276                |
| 307                | 7090-541-6331<br>7090-541-6303          |                   | South I-95 Interchange/Pkwy   | 0                                | 8,047,985                          | 0                     | 8,047,985            | 8,047,985            |
| 461                | 7081-541-6401                           | N/A               | SWU Machinery & Equipment   | 0                                | 0                                  | 32,788                | 32,788               | 32,788               |
| 461<br>461         | 7083-538-6309<br>7083-538-6309          | 17PW06<br>18SU01  | PB Treatment Train in HTC<br>FY 18 Stormwater Utility Program         | 0                                | 82,245<br>704,820                  | (39,649)<br>(704,820) | 42,596               | 42,596               |
| 461                | 7083-538-6309                           | 185001<br>185002  | Riviera Dr @ C-75 Culvert   | 0                                | 20,063                             | (704,820)             | 20,063               | 20,063               |
| 461                | 7083-538-6309                           | 18SU03            | Walden Blvd @ C-42-R Culvert  | 0                                | 21,428                             | 0                     | 21,428               | 21,428               |
| 461                | 7083-538-6309                           | 18SU04            | Pembroke Ave @ C-75 Culvert   | 0                                | 272,561                            | (20,000)              | 252,561              | 252,561              |
| 461                | 7083-538-6309                           | 18SU05            | Weldon St @ C-42-R Culvert  | 0                                | 22,732                             | 0                     | 22,732               | 22,732               |
| 461<br>461         | 7083-538-6309<br>7083-538-6309          | 18SU06<br>18SU07  | Emerson Dr @ C-75 Culvert<br>Fairlight @ C-60 Culvert                 | 0                                | 411,447<br>25,000                  | (70,000)              | 341,447              | 341,447              |
| 461                | 7083-538-6309                           | 18SU08            | Norwood Baffle Box Retrofit   | 0                                | 25,000                             | 0                     | 25,000               | 25,000               |
| 461<br>461         | 7083-538-6309<br>7083-538-6309          | 18SU09<br>18SU10  | Peeble Ave @ C-75 Culvert<br>San Filippo @ C-41-R Culvert             | 0                                | 293,248<br>24,802                  | (20,000)              | 273,248<br>24,802    | 273,248<br>24,802    |
| 461                | 7083-538-6309                           | 18SU11            | San Filippo @ C-42-R Culvert  | 0                                | 21,649                             | 0                     | 21,649               | 21,649               |
| 461                | 7083-538-6309                           | 18SU12            | Rockabye @ C-42-R Culvert   | 0                                | 23,487                             | 0                     | 23,487               | 23,48                |
| ///                | 7083-538-6309<br>7083-538-6309          | 18SU13<br>18SU14  | Powell Sub Drainage Mods<br>Harper Blvd @ C-18 Culvert                | 0                                | 49,277<br>50,000                   | 2,060,000             | 49,277 2,110,000     | 49,277<br>2,110,000  |
| 461<br>461         | /////////////////////////////////////// |                   |   |                                  |                                    |                       |                      |                      |
| 461<br>461<br>461  | 7083-538-6309                           | 18SU15            | San Filippo @ C-9-R Crossing  | 0                                | 99,142                             | (90,000)              | 9,142                | 9,142                |
| 461<br>461<br>461  | 7083-538-6309<br>7083-538-6309          | 18SU16            | Unit 42 Pipe Replacement  | 0                                | 99,142<br>474,750                  | 90,000                | 564,750              | 564,750              |
| 461<br>461         | 7083-538-6309                           |                   |   |                                  |                                    |                       |                      |                      |

# EXHIBIT "A" (Non-Utility Departments)

| Fund        | Department<br>Division | Project<br>Number | Capital Improvements Program Summary                  | FY 2019<br>Adopted CIP<br>Budget | FY 2018<br>to<br>FY 2019 Rollovers | FY 2019<br>Amendments | New Project TOTAL | TOTAL FY 2019 |
|-------------|------------------------|-------------------|---|----------------------------------|------------------------------------|-----------------------|-------------------|---------------|
| 461         | 7083-538-6309          | 19SU04            | PH II Pipe Replacement Unit 42                        | 0                                | 0                                  | 774,500               | 774,500           | 774,500       |
| 461         | 7083-538-6309          | 19SU05            | Replace Pipe Crossing Unit 44                         | 0                                | 0                                  | 7,250                 | 7,250             | 7,250         |
| 461         | 7083-538-6309          | 19SU06            | PH2 Unit 44 Pipe Replacement                          | 0                                | 0                                  | 7,250                 | 7,250             | 7,250         |
| 461         | 7083-538-6309          | 19SU08            | Unit 31 Pipeline Replacement                          | 0                                | 0                                  | 1,105,500             | 1,105,500         | 1,105,500     |
| 461         | 7083-538-6309          | 19SU09            | Unit 32 Pipeline Replacement                          | 0                                | 0                                  | 805,500               | 805,500           | 805,500       |
| 461         | 7083-538-6309          | 19SU07            | Install Cured Pipe 23                                 | 0                                | 0                                  | 520,000               | 520,000           | 520,000       |
| 461         | 7084-541-6401          | N/A               | Vehicle/Equipment Replacement (Machinery)             | 673,000                          | 0                                  | (176,435)             | 496,565           | 496,565       |
| 461         | 7084-541-6401          | N/A               | Survey/Permitting Equipment Improvements              | 27,546                           | 0                                  | 0                     | 27,546            | 27,546        |
| 461         | 7084-541-6403          | N/A               | Vehicle/Equipment Replacement (Light Vehicles)        | 50,000                           | 134,180                            | 0                     | 184,180           | 184,180       |
| 461         | 7084-541-6404          | N/A               | Vehicle/Equipment Replacement (Construction Vehicles) | 301,005                          | 611,486                            | 144,396               | 1,056,887         | 1,056,887     |
| 471         | 7036-534-6211          | N/A               | (1) Carport & (1) Shed (Vehicle/Equipment Shelters)   | 0                                | 0                                  | 8,639                 | 8,639             | 8,639         |
| 521         | 7070-519-6403          | N/A               | Light Vehicles  | 0                                | 322,553                            | 0                     | 322,553           | 322,553       |
| 521         | 7070-519-6403          | N/A               | Replace CIT Vehicle #3203                             | 22,500                           | 0                                  | 0                     | 22,500            | 22,500        |
| 521         | 7070-519-6403          | N/A               | K-9 Conversion/Police Cruiser                         | 0                                | 0                                  | 5,100                 | 5,100             | 5,100         |
| 521         | 7070-519-6403          | N/A               | Police Vehicles - New Acquisition (6)                 | 175,960                          | 0                                  | 0                     | 175,960           | 175,960       |
| 521         | 7070-519-6403          | N/A               | Police Vehicles - Replacements (3)                    | 89,310                           | 0                                  | 0                     | 89,310            | 89,310        |
| 521         | 7070-519-6403          | N/A               | Code Vehicles - New Acquisition (3)                   | 52,920                           | 0                                  | 0                     | 52,920            | 52,920        |
|             |                        | то                | TAL NON-UTILITY DEPARTMENTS ONLY EXCLUDING BCRA       | 5,484,506                        | 24,793,047                         | 3,703,614             | 33,981,167        | 33,981,167    |
| Bayfront Co | ommunity Redevelo      | pment Agen        | cy (BCRA)   |                                  |                                    |                       |                   |               |
| 181         | 9110-559-6301          | 18CR03            | Pelican Harbor  | 0                                | 15,836                             | 0                     | 15,836            | 15,836        |
| 181         | 9110-559-6308          | 18CR06            | Liberia Park (Phase 1 Redesign)                       | 0                                | 19,602                             | 0                     | 19,602            | 19,602        |
| 303         | 3090-541-6101          | 16CR02            | BCRA Redevelopment Plan Projects                      | 0                                | 888,259                            | 0                     | 888,259           | 888,259       |
| 303         | 3090-541-6101          | N/A               | Land Acquisition                                      | 0                                | 0                                  | 153,495               | 153,495           | 153,495       |
| 303         | 3090-559-6305          | 16CR03            | Mooring Field & Dredging                              | 0                                | 103,495                            | (103,495)             | 0                 | 0             |
| 303         | 3090-559-6305          | 18CR01            | Palm Bay Entrance Channel Dredging                    | 0                                | 50,000                             | (50,000)              | 0                 | 0             |
|             |                        | TOTAL BA          | AYFRONT COMMUNITY REDEVELOPMENT AGENCY (BCRA)         | 0                                | 1,077,192                          | 0                     | 1,077,192         | 1,077,192     |
|             |                        |                   | COMBINED TOTAL UTILITY & NON-UTILITY & BCRA           | 13,437,660                       | 34,015,803                         | 4,074,485             | 51,527,948        | 51,527,948    |

### **RESOLUTION 2019-20**

A RESOLUTION OF THE CITY OF PALM BAY, BREVARD COUNTY, FLORIDA, AMENDING RESOLUTION 2018-49, AS AMENDED BY RESOLUTIONS 2018-66 AND 2019-10, ADOPTING THE FIVE-YEAR CAPITAL IMPROVEMENTS PROGRAM FOR THE FISCAL YEARS 2018-2019 THROUGH 2022-2023 FOR THE CITY OF PALM BAY; RESCINDING RESOLUTIONS OR PARTS OF RESOLUTIONS IN CONFLICT HEREWITH; PROVIDING FOR AN EFFECTIVE DATE.

WHEREAS, the City of Palm Bay's Capital Improvements Program, formally known as the Community Investment Program, was adopted by the City Council on September 18, 2016.

WHEREAS, the City of Palm Bay desires to amend the Capital Improvements Program.

NOW, THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF PALM BAY, BREVARD COUNTY, FLORIDA, as follows:

**SECTION 1.** Resolution 2018-49, as amended by Resolutions 2018-66 and 2019-10, is hereby amended by including additional projects to the Five-Year Community Investment Program for Fiscal Years 2018-2019 through 2022-2023, which are, by reference, incorporated herein as Exhibit "A".

**SECTION 2.** This resolution shall take effect immediately upon the enactment date. This resolution was duly enacted at Meeting No. 2019-14, of the City Council of the City of Palm Bay, Brevard County, Florida, on June 20, 2019.

ATTEST

Terese M( Jones, CIT

William Capote, MA